

SPECIFICATION SHEET STYLE: 04526B





Care Instructions

Packed

Case Dimensions (cm)
Case Weight (kg)

Country of Origin Gender

Construction Certifications

Machine Do Not Do Not DryWash Bleach clean

Water temperature 30° C or 80° F, Iron maximum temperature 110° C 230° F, Do not tumble dry

0.00

Men

TAA Compliant

Issaline Rush

Softshell with four taped zips for improved water resistance, detachable hood, three outside pockets and two large inner pockets.

- Four taped zips for improved water resistance
- Ideal for nonwork use
- Detachable hood
- Multipockets